



Dominion

DAM INSPECTION CHECKLIST POSSUM POINT POWER STATION POND ABC

INSPECTION DATE: JANUARY 5, 2016

WEATHER: 27°F, SUNNY

INSPECTED BY: K. ACREE

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	N	N	1130 AM NO WATER AGAINST SANDBAGS
Erosion	N	N	STANDING SAND BAGS IN PLACE WITH SEVERAL RIPPED BAGS RIPRAP IN PLACE
Low Point, B dike*			
Flow	N	N	11:40AM SAND BAGS IN PLACE WITH SEVERAL RIPPED BAGS
Erosion	N	N	NO STANDING WATER AGAINST SAND BAGS
Outfall			
water surface El. (top of stoplogs to water)			NO FLOW AND NO STANDING WATER AGAINST WEIR. ALSO, WEIR WAS ^{IS} DRY, 11:50 AM

* See figure below.

Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.): → STANDING WATER AT TOE OF EMBANKMENT (TYPICAL OF ALL PONDS)

→ STANDING WATER AT TOP OF EMBANKMENT ~~BETWEEN POND~~ AS NOTED BELOW.

→ SAND BAGS AT LOW POINT OF DIKE OF POND C ARE IN PLACE WITH SEVERAL RIPPED BAGS

